

Hasselblad A/S
July 11, 2011

Camera Viewfinder Firmware: Version VF110701.hbf for HVD90x & HVx90-II

Firmware version VF110701.hbf requires one of the above mentioned Hasselblad viewfinders

Compatibility

Product	Firmware Version
HVD90x, HV90x-II	2.2.0

Highlights

New features for **H4D-60**:

- Added new graphics for the Electronic spirit level function

No added functionality on other cameras

Installation

Connect the camera to the host computer using a FireWire cable. Leave lens and viewfinder on the camera body. Make sure the computer is powered from the mains supply or has a fresh battery.

Start Phocus and when the camera is connected, as indicated by an active camera icon in the top left part of the screen, select "**Update Firmware...**" from the "**File**" menu. Browse to the location where the update file was saved and follow the instructions on screen. The update procedure will take a few minutes to finish. Depending on camera model, different options will be available during the update process.

Limitations

This firmware is not to be used with other Hasselblad viewfinders than the ones listed above.

Firmware updating is only possible via Phocus version 1.1.3 Mac, 1.0.2 Windows (or later).

Please be aware that H4D camera models require Phocus 2.0 (or later) in order to function properly and H4D-60 requires Phocus 2.5.5 or later.

Do not use a PC laptop to perform this firmware update, as the firewire providence (it's ability to provide enough power) may be to low. Attempts may render the sensor unit unbootable. Should you experience this problem then perform the update on a stationary PC. This problem is not related to Mac computers.

Change Log