

Firmware 0.5.6 for Hasselblad XCD Lenses

The 0.5.6 release is a maintenance release for the X1D-50c camera that solves a bug related to flash sync.

Improvement:

- Solves an issue where rear flash sync didn't work with shutter speeds longer than 2 seconds.

Update procedure


Mount the lens on the camera to perform the update. Repeat the process for all XCD lenses.

Make sure that you use a fully charged battery on the camera. A charge level of 50% or more is required. Please note that the update procedure normally takes up to 1 minute.


Note: It is not allowed to have the USB cable inserted during the update process.

Note: Once the update is completed you must remove and reinsert the battery.


Copy the downloaded file (X-Lens_v0_5_6.cim) to the SD card and insert it into the camera. Then follow the procedure below:



1: Select the "Settings Menu" from the main menu.



2: Select "Service"



3: Click "Check for update" and select the file "X-Lens_v0_5_6.cim" from the list. Finally click "Upgrade".

September 7, 2017 / The Hasselblad Team