

Hasselblad A/S May 23, 2013

Firmware version 1.5.3R for H5D-40 & H5D-50

This package contains firmware version 1.5.3R.CIM for the above listed products.

Changes since version 1.2.0R:

New features:

- Nine image view now available
- Visual indication of overexposed areas in the image (Mark overexposure) now available
- Chinese language support

Numerous bug fixes and stability improvements

(For a historical list of firmware changes, please see the change log at the bottom of this document.)

Installation

Manual updating of firmware is available in the Phocus software, from version 2.7 Mac and 2.7 Windows.

Procedures for updating capture unit firmware via the Phocus software:

1. Unzip the downloaded file.
2. Make sure your camera is turned on.
3. Connect your complete camera, including the capture unit, lens and viewfinder to Phocus using a **POWERED** Firewire cable.
3. Go to "**File**" and then "**Update Firmware**" and locate the desired firmware package (**firmware_1.5.2R.cim**) on your computer, and click "Update".
4. Follow the instructions provided from the software carefully! Do not switch off the camera during the update process, unless specifically requested by the Phocus software.
5. When the update has been finalized, please restart your camera and check that the firmware has been successfully updated.

IMPORTANT NOTICE: During the upgrade procedure do NOT disconnect the firewire cable until prompted! After installing 1.5.3R you should proceed to install Camera Body Firmware H5D130506.hbf

Unintentionally removing the Firewire cable during the firmware download procedure could in worst case render the camera useless which would require the need for authorized service.

Change Log:

Changes in version 1.2.0R:

New features:

- Improved color rendition in high ISO JPEG
- Various Graphical User Interface improvements
- Performance improvements